



Donic Independent Engineering Services  
Unit 3/14 Ardmillan Road  
Moonee Ponds VIC 3039  
(ABN 63 257 734 370)  
P: 03 9375 1852  
F: 03 9370 8934  
M: 0418 360 354  
E: donic77@bigpond.net.au

15 March 2021

**CERTIFICATE OF INSPECTION AND TESTING OF "CONCRETE PLACING UNIT" (CPU)**  
**MAJOR INSPECTION / ASSESSMENT**

Type of CPU:	Truck Mounted	Certificate No:	21 / 153 / 2
CPU Model Manufacturer:	Putzmeister Pty Ltd	Model No:	47M
CPU Serial No:	170603403	ESANDT NDT Report No's:	ET7852-KCP21 UT6790-KCP21
QLD Road Registration No:	TBA	Year of manufacture:	2012
QLD Plant Registration No:	TBA		

Owner's name:	Kaboom Concrete Pumping Pty Ltd		
Address:	6 Derwent Street, Sippy Downs QLD 4556		
Interim inspection date on site:	15 March 2021		
Name of competent person:	Donald Charles Nicholls		
Address of competent person:	3/14 Ardmillan Road, Moonee Ponds, Vic, 3039		
Telephone No:	03 9375 1852	Fax No:	03 9370 8934

**Qualifications of Competent Person**

Professional engineering qualification, membership of professional organisation and 40 years' crane industry experience.

**Competent Person Statement**

I hereby state that the above Placing Boom serial number **170603403** has received its structural major third-party inspection in accordance with the recommendation of the manufacturer and with relevant Australian Standard Standards and is safe for use provided it is operated and maintained in accordance with the manufacturer's recommendations and Australian Standards AS 2550 Part 15 2004, AS 1418.15.

**The CPU shall be submitted for its next third-party annual inspection at (1) year (3 / 2022) and a further major inspection / assessment after a period of six (6) years (3 / 2027).**

Competent person signature

D.C. Nicholls C.P. Eng



Donic Independent Engineering Services will not accept any responsibility for the mechanical condition of the CPU beyond the date indicating the time the CPU conformed to the checklist. Maintenance records must be maintained by the client beyond this date. Please note, the level of further inspections will be dependent upon the level of maintenance records produced by the owner of the CPU. (Donic Ref D2885)