

Kaboom Concrete Pumping

kaboomconcretepumping@gmail.com

0450 511 115

ABN 84 746 216 542

Saturday, November 23, 2024
Tim Lane
24074
24500
1281
Na
~
\checkmark

1st To 2nd Stage link

Pivot pins	\checkmark
Ram pins	\checkmark
2nd hyd cyl cracks, oil leaks	\checkmark
Linkage pins	\checkmark
Cracks in linkages	\checkmark
Lock plates, split pins etc.	\checkmark

Stage 2 Inspection

Check for cracks	\checkmark
All pipe supports/brackets/clamps	\checkmark

2nd To 3rd Stage Link

Pivot pins	\checkmark
Ram pins	\checkmark
3rd hyd cyl cracks, oil leaks	\checkmark
Linkage pins	\checkmark
Cracks in linkages	\checkmark
Lock plates, split pins etc.	\checkmark

Stage 3 Inspection

Check for cracks	\checkmark
All pipe supports/brackets	\checkmark

3rd To 4th Stage Link

Pivot pins	\checkmark
Ram pins	\checkmark
3rd hyd cyl cracks, oil leaks	\checkmark
Linkage pins	\checkmark
Cracks in linkages	\checkmark

Lock plates, split pins etc.	\checkmark

Stage 4 Inspection

Check for cracks	\checkmark
All pipe supports/brackets	\checkmark

4th To 5th Stage Link

Pivot pins	\checkmark
Ram pins	\checkmark
4th hyd cyl cracks, oil leaks	\checkmark
Linkage pins	\checkmark
Cracks in linkages	\checkmark
Lock plates, split pins etc.	\checkmark

Stage 5 Inspection

Check for cracks	\checkmark
All pipe supports/brackets/clamps	\checkmark

Outriggers Legs Base

Cracks in base pedestal	\checkmark
Cracks in outrigger legs	\checkmark
Lock nuts split pins	\checkmark
Lock plates (for all rams and legs)	\checkmark
Inspect Dunnage (timbers) pads and timbers	\checkmark

Ears & Slew Mechanism

Check slew motor for tightness	\checkmark
Inspect for cracks in ears and base weld	\checkmark
Inspect slew ring gears/rack and pinion	\checkmark
Visual inspection slew ring bolts	\checkmark

Turn Pipes As Necessary And Record Details On Pump Maintenance Record

Grease all nipples, boom and truck as per diagram (multi-purpose grease)	~
Check battery level (distilled water)	\checkmark
Check all fluid levels	\checkmark
Clean inside windscreen (windex)	\checkmark
Inspect reducers and hoses for wear/damage and report	\checkmark
Clean machine inside and out	\checkmark
Inspect clamps operation and numbers (2 of each)	\checkmark
Fill consumables (snot, shackles, rope, duct tape, safety clips, sponges)	\checkmark
Check lights, blinkers, flashing lights, estops etc.	\checkmark
Clean a/c filter	\checkmark
Fill Auto Greaser (EPOO Grease)	\checkmark
Inspect for leaks/loose bolts (pto, drive shaft, uni's etc.)	\checkmark
Clean water box and turn pistons	\checkmark
Test air pressure in all tyres (100psi)	\checkmark
Advise supervisor of any defects	\checkmark
Fill out paperwork and return to office	\checkmark
Rego Number	47put5
Make of Pump	Putzmeister
Boom Size	47mt
Service Due	24500

Month Nov

Year 2024